

| Vines Afectados Tahoe etiqueta caja de fusibles |                   |
|---|-------------------|
| 1GNSK6KC0FR541154                               | 1GNSK6KC4FR616633 |
| 1GNSK6KC6FR542700                               | 1GNSK6KC5FR618682 |
| 1GNSK6KCXFR571326                               | 1GNSK6KCXFR505150 |
| 1GNSK6KC3FR504454                               | 1GNSK6KCXFR545065 |
| 1GNSK6KC0FR505190                               | 1GNSK6KC0FR501267 |
| 1GNSK6KC0FR539288                               | 1GNSK6KC7FR500620 |
| 1GNSK6KC2FR545089                               | 1GNSK6KC6FR573302 |
| 1GNSK6KC3FR503367                               | 1GNSK6KC6FR573607 |
| 1GNSK6KC6FR576541                               | 1GNSK6KC7FR543757 |
| 1GNSK6KC7FR502853                               | 1GNSK6KC8FR620099 |
| 1GNSK6KC0FR503844                               | 1GNSK6KC3FR502638 |
| 1GNSK6KC3FR500601                               |                   |