

Vines afectados Cruce reprogramación módulo ECM			
KL1PJ5C54EK543158	KL1PJ5C54EK549168	KL1PJ5C56EK566358	KL1PJ5C50FK000049
KL1PJ5C52EK543305	KL1PJ5C54EK548537	KL1PJ5C51EK566008	KL1PJ5C51FK000075
KL1PJ5C53EK542163	KL1PJ5C5XEK549272	KL1PJ5C56EK567199	KL1PJ5C52FK000103
KL1PJ5C55EK543864	KL1PJ5C55EK558929	KL1PJ5C53EK580749	KL1PJ5C59FK000115
KL1PJ5C51EK542386	KL1PJ5C5XEK559879	KL1PJ5C58EK580939	KL1PJ5C59FK000079
KL1PJ5C59EK543835	KL1PJ5C51EK557731	KL1PJ5C54EK578640	KL1PJ5C57FK000128
KL1PJ5C59EK542670	KL1PJ5C50EK560099	KL1PJ5C5XEK579758	KL1PJ5C51FK000061
KL1PJ5C52EK543692	KL1PJ5C57EK559516	KL1PJ5C5XEK579470	KL1PJ5C58FK000087
KL1PJ5C59EK541986	KL1PJ5C50EK556652	KL1PJ5C51EK579034	KL1PJ5C58FK000106
KL1PJ5C5XEK543567	KL1PJ5C51EK558068	KL1PJ5C52EK579172	KL1PJ5C57FK000081
KL1PJ5C52EK544101	KL1PJ5C56EK558454	KL1PJ5C55EK578582	KL1PJ5C55EK583362
KL1PJ5C58EK544460	KL1PJ5C56EK559085	KL1PJ5C52EK579804	KL1PJ5C5XEK583616
KL1PJ5C5XEK541575	KL1PJ5C50EK558532	KL1PJ5C51EK580054	KL1PJ5C54EK584275
KL1PJ5C55EK542150	KL1PJ5C56EK557580	KL1PJ5C54EK580131	KL1PJ5C54EK583935
KL1PJ5C59EK542359	KL1PJ5C57EK557765	KL1PJ5C50EK580868	KL1PJ5C58EK582979
KL1PJ5C59EK542846	KL1PJ5C59EK566032	KL1PJ5C56FK000119	KL1PJ5C50FK000178
KL1PJ5C50EK541746	KL1PJ5C50EK566050	KL1PJ5C53FK000076	KL1PJ5C53FK000238
KL1PJ5C5XEK543682	KL1PJ5C59EK567357	KL1PJ5C54FK000071	KL1PJ5C57FK000176
KL1PJ5C52EK542154	KL1PJ5C55EK567226	KL1PJ5C50FK000097	KL1PJ5C57FK000212
KL1PJ5C58EK541736	KL1PJ5C57EK566790	KL1PJ5C56FK000069	KL1PJ5C57FK000193
KL1PJ5C55EK541564			