

Vines afectados Captiva reprogramación velocímetro		
KL1FC5C43BB134576	KL1FC6C53DB043843	KL1FC6C50DB077481
KL1FC5C47BB135343	KL1FC6C56DB048907	KL1FC6C55DB078061
KL1FC6C53CB043212	KL1FC6C58DB049461	KL1FC6C57DB078465
KL1FC6C55CB044555	KL1FC6C50DB050247	KL1FC6C58DB090446
KL1FC6C54CB075263	KL1FC6C50DB055092	KL1FC6C55DB095829
KL1FC6C55CB078169	KL1FC6C54DB055872	KL1FC6C54DB098544
KL1FC6C52CB094829	KL1FC6C50DB055982	KL1FC6C50DB107904
KL1FC6C52CB095401	KL1FC6C53DB056818	KL1FC6C57DB107978
KL1FC6C57CB096687	KL1FC6C51DB057286	KL1FC6C54DB109199
KL1FC6C5XCB097848	KL1FC6C57DB060404	KL1FC6C55DB109888
KL1FC6C53CB098663	KL1FC6C58DB060816	KL1FC6C53DB110246
KL1FC6C57CB103136	KL1FC6C52DB062545	KL1FC6C51DB111153
KL1FC6C57CB105162	KL1FC6C54DB062532	KL1FC6C59DB111188
KL1FC6C59CB116311	KL1FC6C51DB063797	KL1FC6C50DB112309
KL1FC6C54CB116474	KL1FC6C51DB065176	KL1FC6C50EB023079
KL1FC6C50CB116570	KL1FC6C52DB070032	KL1FC6C51EB037461
KL1FC6C59CB116714	KL1FC6C51DB070250	KL1FC6CG1BB000133
KL1FC6C50CB117444	KL1FC6C54DB069691	KL1FC6CG3BB000134
KL1FC6C52CB117655	KL1FC6C58DB070889	KL1FC6CG5BB000135
KL1FC6C56CB118419	KL1FC6C54DB074485	KL1FC6CC8BB006377
		KL1FC2CU6EB000048