

Vines afectados Tahoe 2015-2016 Programación	
1GNSK6KC6FR542700	1GNSK6KC3FR500601
1GNSK6KCXFR571326	1GNSK6KC4FR616633
1GNSK6KC0FR541154	1GNSK6KCXFR505150
1GNSK6KC3FR502638	1GNSK6KCXFR545065
1GNSK7KC8GR284834	1GNSK6KC5FR618682
1GNSK7KC0GR286271	1GNSK7KC2GR423436
1GNSK7KC9GR313418	1GNSK7KC3GR421887
1GNSK7KC7GR279950	1GNSK6KC0FR501267
1GNSK7KCXGR282535	1GNSK7KC8GR283098
1GNSK6KC0FR505190	1GNSK6KC3FR504454
1GNSK6KC0FR539288	1GNSK6KC6FR573302
1GNSK6KC3FR503367	1GNSK6KC6FR573607
1GNSK6KC6FR576541	1GNSK6KC7FR500620
1GNSK6KC7FR502853	1GNSK7KC4GR284202
1GNSK6KC2FR545089	1GNSK7KC2GR312627
1GNSK6KC0FR503844	1GNSK6KC8FR620099
1GNSK7KC8GR281240	1GNSK6KC7FR543757
	1GNSK7KC4GR285494