

| |
|---|
| Vines afectados Camaro reemplazo perno regulador de altura de asiento |
|---|

| |
|-------------------|
| 2G1F91ED3B9182294 |
| 2G1F91ED4B9166699 |
| 2G1F91ED5B9117818 |
| 2G1F91ED6B9114376 |
| 2G1F91ED7B9130375 |
| 2G1F91ED8B9129848 |
| 2G1F91ED9B9181117 |
| 2G1F91EDXB9166013 |